

to undergo a Special Survey No.3.

6E

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

31 OCT 1922

S NAME

Ballabor

Rpt.

Rija

No.

1702.

marks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

DAMAGE TO ENGINES AND BOILERS.

This vessel is reported by the

Rija

Surveyor

to have sustained damage to

machinery


through *being submerged.*

Temporary repairs have been effected to his satis-

faction to enable her to ~~proceed on her voyage to~~ *be towed to the U.S. on Continent.*

The Surveyor recommends *further examination & repairs on arrival at a repairing shop.*

It is submitted *action be deferred.*



Lloyd's Register
Foundation

005840-005848-0084

to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in the Register Book or other publication of the Society, or for any error of indolence, default or negligence of any of its