

1

14 JUN 1922

Sent to Chief Surveyors 13.7.22 Received from Chief Surveyors _____
 VESSEL'S NAME sp "Lombard" Report Don No. 85645^a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Boiler When due 6.22

The boiler survey became due in 6.22 no part has been held.

The Owners have requested that the vessel's class be withdrawn from the Register Book & three dots inserted in lieu thereof.

It is submitted that this should now be done.

Withdraw class.
 Insert . . .

[Handwritten signature]
 13/7/22
[Handwritten signature]



© 2020

Lloyd's Register
 Foundation

005914-005928-0104