

Nov. 28/19.

CABLEGRAMS: NYMDIBLE, NEW YORK

TELEPHONES { 220 } WHITEHALL
 { 221 }
 { 222 }

LLOYD'S REGISTER OF SHIPPING,
17 BATTERY PLACE

NEW YORK, December 1st, 1919.


Mr. J. Robinson,
Hotel Wayne,
Erie, Pa.

Dear Sir:-

With reference to the top half of the exhaust casing for the Skinner & Eddy Corporation which was found to be defective and was repaired by screwing plugs into same, I have to inform you that in order to avoid delay in delivery, the Owners have agreed to accept this casing on the understanding that the manufacturers are to renew the casting if at any time in the future it fails.

I shall be glad if you will be guided accordingly.


Yours very truly,



Secretary.

J.R.
3/12/19.

EMS/RT



© 2021

Lloyd's Register
Foundation

005443-005460-0047
005443-005460-0050

Diagonal thrust
59.5
age and Don
St. Tunnel
room & size
always acc
keep water
ss covering
Room Ca
Deck
Marine
te
n of Saf
with easin
shell pla
seams
straps
Back
le diam
ming n
E
we by
lates
of st
botto
e b
t
of st
eZ
A
e jo
hol
How stayed
review by Hydraulic Pressure to