

of "Tokushima Maru".

Grk. Rph. No 16538

It is submitted that the Greenock Surveyors  
attention be drawn to an error in their letter  
of the 26<sup>th</sup> inst. where they state the tensile  
strength of the shell is  $2\frac{1}{2}$  tons minimum &  
they should be asked to state whether this  
should be  $28\frac{1}{2}$  tons minimum.

Lr. 29.9.13

*(JW)*  
19/9/13  
Lloyd's Register  
Foundation  
005943-005960-0065