

Less
Less

Im. 12. 15.

~~Rothen~~ Rothenⁿ

Disclass Section 130

F.E.

Received by Chief Ship Surveyor 13. 6. 17.

Received from Chief Ship Surveyor

VESSEL'S NAME Shells "Anthony Aslett" Rpt. Shel No. 29993

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 36.53

Depth "d" 11.83

Framing: Table No. 3 page 9

Description Single Angles as appended.

Longitudinal No. 4748

Proportions $\frac{\text{Length}}{\text{Depth}} = 9.87$

~~Deck~~ Sheerstrake -62 of an web instead of .36 as required.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed  100 A-1. (Steel) Steam Trawler. as recommended.

I.D.K.

B.K. 8. A.B.H. Cen. Lloyd's Reg. 273. Feb.

M.
14. 6. 17



© 2021

Lloyd's Register
Foundation

005995-006015-0183

BEAN