

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

14th April, 1921.

Dear Sir,

S. Reverting to your letter of the 5th February respecting the classification in this Society's Register Book of your Aux. Screw Schooner "SANTA ANNA", I am directed to acquaint you that the Committee have now had before them a letter received from the Society's Surveyor at Seville from which it appears that no definite arrangements have been made by your goodself for the submission of the oil engines to inspection.

In the circumstances, and in view of the fact that the survey in question became due so long ago as May last, the Committee regret that they have no alternative but to expunge the vessel's class from the Register Book with a red line, indicating non-compliance with the Society's Rules.

I may add that upon receipt of a satisfactory report from the Society's Surveyors to the effect that the necessary survey has been carried out, the case of this vessel will be eligible to be submitted to the Committee with a view to the reinstatement of her character.

Manuel Rio-Sarmiento, Esq.,

I am, Dear Sir,
Yours faithfully,