


2 Screws aft + 1 Forward = 3 screws

T. 6 Cy  $21\frac{1}{2}$ ,  $35\frac{1}{2}$ ,  $\pm 58 - 36$  (aft)

T. 3 Cy  $18\frac{1}{2}$ ,  $30\frac{1}{2}$ ,  $\pm 50 - 36$  (for)

(JWD), 4/12/19



© 2020

Lloyd's Register  
Foundation

006056.006066-0028