

Im. 12.15.

F.E.

Received by Chief Ship Surveyor 17.11.17

Received from Chief Ship Surveyor

VESSEL'S NAME Steel Yacht "Robert Bookless" Rpt. Due No. 30245

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 37.12

Depth "d" 12.16

Framing: Table No. 3 page 10

Description Single angle as app<sup>d</sup>

Longitudinal No. 5134

Proportions Length = 10.24  
 Depth

Deck Sheerstrake .62 of an inch instead of .38 as required.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✱ 100 A1 (Steel) Steam Trawler. as recommended.

1194  
 BK 7½" 4 BH. Cem.  
 Leys A + CP.  
 Q 78' F 19'

M  
 17.11.17



© 2021

Lloyd's Register Foundation

006080-006095-0238