

19 APR 1945

"APPLELEAF"

Sld. 34166.

BS due 12.44 held and machinery generally examined.

Some distorted furnaces faired in forward boilers and stiffening rings fitted on distorted furnaces in after section of boilers.

It is recommended that the furnaces of the port and starboard boilers of the after section be examined or renewed before the end of 9.45.

It is stated the vessel will be used as a mobile store ship at Iceland where only one section of boilers will be used at any one time and in this case the limit on the furnaces could be extended for 1 year.

It is submitted the record BS 3.45) need not be withheld.
Examined 3.45)

Subject as recommended.



© 2021

Reith
18.4.45

Lloyd's Register
Foundation

006140-006147-0039