

ived by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

SSSEL'S NAME

"APPLELEAF".

Rpt. H.Kg.

No. 7867.

he remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.)

ture of Survey SPECIAL SURVEY OF ENGINES AND/OR BOILERS PARTLY HELD FOR S.S. No
& ALTERATIONS.

~~LMC~~

~~LMC (M)~~

due 7,37 , partly held now.

~~MS~~

BS

~~was further advanced~~ and the following repairs effected (due to wear and tear

All stay tubes renewed in the three after boilers.

Centre furnace of centre boiler renewed.

Boilers tested satisfactorily.

It is proposed to complete the survey (not stated).

Alterations. 4 circular tanks have been fitted in accordance with the approved plans.

It is submitted that ~~this proposal merits approval and~~ the vessel is eligible to remain as classed, and WILL BE eligible for the record

BS 7,37 when the survey has been completed.

The following remains to be done to complete the Survey

Adjust safety valves of the three forward boilers.

YKw

23.9.37.



© 2021

Lloyd's Register
Foundation