

COPY.

Lloyd's Register of Shipping.



Port Hong Kong

31st. July 1937.

This is to Certify that I have

Surveyed the Twin S.S. "APPLELEAF" of London, 5892 Gross Tons,
No.70628 in the Register Book, for Condition, Completion of
S.S.2nd.No.2., Renewal of Freeboard and Alterations.

and that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report, stating that all repairs
recommended by me have been completed to my satisfaction, and
that I have Recommended that she be continued as classed
with fresh record of survey 7-37. Subject to indented plating
Starboard side in way of No.1 tank and bottom plating (P. S.)
and stern plating etc. being repaired at Owner's convenience,
The notation of S.S.2nd.No.2-37.
being fit to carry Petroleum in bulk.

Survey fee - - - - \$185.00.
S.S.No.2. - - - - \$200.00.
Alterations - - - - \$200.00.
Repairs - - - - \$ 50.00.
Selling expenses \$ 20.00.

J. Morrison

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—
While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly
performed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances
to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any
entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its
Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."