

Received by Chief Ship Surveyor 22.4.18

Received from Chief Ship Surveyor 24 APR 1918

VESSEL'S NAME Steel T/s/s "Appleleaf" Rpt. Mdb No. 10078

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

DAMAGE.

Damage through encountering a mine & through settling on
bidge blocks when docking for temporary repairs.
now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed	23	32		3	7	1	9
Removed and faired or repaired.....	6	13			2		
Faired or repaired in place.....	8	3					

Other items:- Tank bulkheads repaired as necessary and a
number of minor repairs effected.
Bottom cleaned examined & coated.

It is submitted the vessel is worthy to remain as classed with
record of Survey 4.18 as recommended

100 A1 "Carrying petm in bulk".
4.18 Mdb.



© 2021

Lloyd's Register
Foundation

006140-006147-0062