



LLOYD'S REGISTER
LONDON.

FEB 15 1917

16

Lloyd's Register of Shipping,

97 & 98, Scottish Provident Buildings,
Donegall Square West,
Belfast, 14th February 1917.

Secretary,

I beg to enclose the Special Certificate for R.F.A. "TEXOL", now named "APPLELEAF" duly signed. The Admiralty have ordered the 5 1/4" cream steel wire to be returned to the Dockyard.

This wire is required by our Rules for Classification but there are two 4 1/2" and two 4" wires on board, and the Towlines, Hawsers and Traps are complete apart from the above.

Please state if this is considered satisfactory.

I am, Sir,

Your obedient Servant,

C. F. Beveridge
per Lunnell



© 2021

Lloyd's Register
Foundation

006140-006147-0082

Lloyd's Register of Shipping

97 & 98, Scottish Provident Buildings,
Dorset Hill Square West,

Belfast, 14th February 1917.

The Secretary,

I have to advise the Special Certificate No. 1170, now
issued under the Act of 1914, has been ordered to be
renewed. The certificate was issued to the vessel
on 14th February 1917. The vessel is owned by the
British Overseas Airways Corporation and is
operated by the British Overseas Airways Corporation.
The vessel is a passenger vessel and is licensed to
carry passengers. The vessel is licensed to carry
passengers and is licensed to carry passengers.
Please state if this is considered satisfactory.

I am, Sir,

Your obedient servant,

W. J. [Signature]

SECRET & CONFIDENTIAL

Referred to the Chief Surveyors

W. J. [Signature]

FEB 20 1917



© 2021

Lloyd's Register
Foundation