

8m.6.11

Sent to Chief Surveyors 1. 2. 24.

Received from Chief Surveyors - 4 FEB 1924

VESSEL'S NAME

s/s "Chios"

Report

Low

No. 87453^a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

Nature of Survey

Screw shaft

When due

10. 23.

The examination of this vessel's screw shaft became due in 10. 23.

The Owners state that they propose to convert the vessel to a repair ship & therefore being a Greek warship. she will be no longer classed.

It is submitted that the vessel's class be withdrawn from the Register Book & three dots inserted in lieu thereof, indicating that the class has been withdrawn at the request of the Owners.

Withdraw class.

Insert ...

AWD
1/2/24



© 2020

Lloyd's Register Foundation

06248-06257-063

Classing