

2m.8,21.

10 OCT. 1921

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Steel S.S. "BRADAVON". Rpt. Len. No. 84712a

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

Nature of Survey

The class of this vessel is subject to some indented plating and damage through collision being repaired at the first opportunity.

The Owners now state they wish to withdraw the vessel's class from the Society's Register Book.

It is submitted the vessel's class be withdrawn from the Register Book and three dots (...) inserted in lieu thereof, indicating withdrawal of class at the Owners' request.

*Withdraw class
Insert ...*

 © 2020
Lloyd's Register
Foundation
8. 10. 21.
00672-006730-0167