

"EMPIRE CONVOY" (ex "Levenson")

Ex German Vessel.

Hul. 53040.

A General Examination of machinery and Boiler Survey have been held.

Vessel examined in dry dock but screwshaft has not been drawn. The wear down is satisfactory.

Some electrical repairs have been effected but other recommended repairs are deferred until vessel's return in about 2 weeks.

It is submitted for favourable consideration that the Records Examined LR 8.45 BS 8.45 (185 lbs) be assigned subject to electrical equipment being repaired as recommended.

Lloyd's Register
Foundation
Reel

26-9-45.