

MEMORANDUM

COPY

From: LLOYD'S REGISTER OF SHIPPING, 71, FENCHURCH STREET,
LONDON, E.C.3.

(Ref. H.)

The Surveyor(s) at HONG KONG.

Date: 27th September, 1946.

Vessel's Name: S.S. "SPARTAN".

Question: I have to acquaint you that in June last the Port Said Surveyor reported that a furnace crack had been repaired by welding.

It was recommended that the inboard furnace of the starboard main boiler should be specially examined on the waterside at Hong Kong, and as the vessel is understood to have been at your port last month, I shall be glad to learn how this matter stands.

Answer:

Date:



© 2021

Lloyd's Register
Foundation

006281-006291-0241