

28 FEB 1974

to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

T. L. L. Live Amad

Report

Lm

No. 87547A

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Screw Shaft

When due

1.24.

The screw shaft became due for survey at the end of last month & in reply to enquiry the Liverpool Office now forwards a letter received from the Owners in which they state they do not intend to continue the classification of the vessel.

It is submitted that the vessel's class be withdrawn from the Register Book & three dots (...) inserted in lieu thereof indicating withdrawal of class at owners request.

Withdraw class
Insert ...

J.L.

27/2/24

PMS

P.M.

M.S.



© 2020

Lloyd's Register
Foundation

006317 006331 0018