

Steel Screw Sloop "GRINKLE"; No. 71158 in the Register Book;  
322 tons gross; Built in 1914 - 8 mo.;

Owners: William Cooper & Sons, Limited.

Classed:

\* 100A1

Lighter

12,23

s.s.No.2-22

\* LMC 12,22

BS 12,23

TS 12,22

In April last this vessel was reported to have sustained damage to the bottom plating, etc. through grounding, and it was recommended that she should be dry docked and repairs carried out at the end of May last. The engine and thrust seatings also required to be specially examined and some indented plating dealt with.

The vessel has recently been sold, and the new Owners now state that she is working in the upper reaches of the River Mersey and is not likely to be sent to sea. They add that they are unable to spare the time to have the necessary repairs and renewals effected.

The circumstances received the consideration of the Classing Committee on Tuesday, 22nd instant, when it was decided to give instructions for the vessel's character to be withdrawn from the Society's Register Book and three dots (...) inserted in lieu thereof, indicating withdrawal of class at Owners' request.

*TAM*  
24th July, 1924.



© 2021

Lloyd's Register  
Foundation