

F.E.

Received by Chief Ship Surveyor 20.8.14

Received from Chief Ship Surveyor

VESSEL'S NAME

Sheels Grinkle

Rpt.

MC

No.

66535

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

36.2

Depth "d"

8.83

Framing: Table No.

3 page 9

Description

Bulb angle as approved

Longitudinal No.

4996

Proportions

Length

Depth =

~~Deck~~ Sheerstrake . 50 of an inch instead of .48 as reqd.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ✱ 100A-1. (Steel) Lighter, as recommended

✱ 100A-1. (Steel) Lighter

15K (Steel)

WTB = FPT 40L APT 23L.

FK. 3BK. Cen Lloyd's Reg. F 17. Mach abt.



© 2021

Lloyd's Register
Foundation

006332-006342-0199