

1

Sent to Chief Surveyors

Received from Chief Surveyors 10 APR 1924

VESSEL'S NAME Stl. Se. "GOLDENFELS"

Report Brm. No. 702

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/02.)

Nature of Survey

When due

The Boiler Survey became due 2,24 and the survey of the Screw Shaft 3,24.

The Owners now state they do not wish to retain the classification, the vessel being classed with the Germanischer Lloyd.

It is submitted the vessel's class be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw Class
Insert ...


8.4.24.



© 2021

Lloyd's Register
Foundation

006358-006368-0023