

Chief Surveyors

16. 9. 21.

Received from Chief Surveyors

17 SEP. 1921

VESSEL'S NAME

s/s "Monte Cristo."

Report

Don.

No. 84627^a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey

When due

This vessel's class was continued subject to the bearing & bracket of the pump lever rocking shaft being renewed on the vessel's arrival at a home port.

A letter has now been received from the Owners requesting that the class of the vessel be removed from the Register Book.

It is submitted that this vessel's class be withdrawn from the Register Book & three dots inserted in lieu thereof indicating that the class has been withdrawn at the Owners' request.

Withdraw class.

Insert ...

AWD.
16/9/21
CWS
M



© 2020

Lloyd's Register
Foundation

006369-006386-0243