

COPY.

Lloyd's Register of Shipping.



Port MANILA, P. I.


November 16th, 1923.

This is to Certify that I have

Surveyed the Bow Plating in fore peak of the British s/s


"CAPELHALL" of Dundee, 1378 Tons Net, No. 16905 in Register

Book

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, and that I have Recommended that she be continued as at present classed  100 A1 subject to permanent repairs being carried out at destination

being fit to ~~comm~~ proceed on her voyage to Japan.

Survey Fee £100.00


Surveyor to Lloyd's Register.

ertificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood
Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or
by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error
fault, or negligence of the Surveyors, or other Officers or Agents of the Society."