

Chief Surveyors

Received from Chief Surveyors

SHIP'S NAME Steel SS "CITY OF VERNON" Report Pensacola No. 54

For the CHIEF SHIP SURVEYOR ~~CHIEF ENGINEER CERTIFICATE~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24 Feb.)

Survey

When due

The Downton Pump has been dispensed with for the present.
Anchors tested by American Bureau Surveyors.

100 A.1. (steel)

2 Dks (steel) & Webframes.

Cell DB 338' 1305t. MT 27' 830t. FPT 104t. APT 136t.

FK. 7 BH. Cem. C.P. P36', B124', F44'


10. 14/8/20

[Signature]

AEB.
9-7-20

It is concluded the riveting in the hulls of ~~sheerstrakes~~ clear of bridge, is as joined & that the Chain Cables have been tested by one of the Society's Surveyors & the Surveyor should be requested to state if this is so. He should also state date of launch.

*no hulls
20/9/20*



Lloyd's Register
Foundation

006412-006422-0234