

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

5-MAR 1920

VESSEL'S NAME *SS S. Janme & Tours* Rpt. *Off* No. *41886*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

RE-instated. DAMAGE.

The class of this vessel was
expunged and struck 12.18
inscribed in Register Book.

Damage through

Shifting

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed	93	92	8	77			
Removed and faired or repaired.....	24	188	94	44			
Faired or repaired in place.....	32	16	72	1			

Other items:-

Vessel examined in Dry Dock. Stem frame renewed.
Bulldoz repairs & four pintles renewed. Tank top plating,
bulkheads, Centre girder, intercostals, bracket floors etc.
Repairs & renewed as necessary & minor repairs effected.
A tower anchor & 15 fms. of cable of proper size weight
& list supplied, remainder of anchor & cables collected.

It is submitted the vessel is worthy to ~~remain as classed with~~ have her class reinstated in the R.B.

With record of Survey 1-20 as recommended

RE-instated
100 A.1

1-20 Off

Lloyd's A & B.

The Surveyors should be requested to forward forgoing report
for stem beams.