

COPY.

Lloyd's Register of British & Foreign Shipping,

71, Fenchurch Street, E.C.

18th January 1913.

Gentlemen,


With reference to the case of the steel screw steamer No. 507 built by Messrs. Hall, Russell & Co., see your report No. 10908, I have to inform you that a report has been received from the Society's Surveyors at Hull, from which it appears that the machinery has been fitted, but that with regard to the pillars recommended to be fitted as per your report, Messrs. Earle's Shipbuilding & Engineering Co., who have fitted the machinery, state that they have received no instruction to carry out this work.

I have therefore to request that you will arrange with the Builders for these pillars to be fitted, and I shall be glad if you will let me know by return what action is being taken in the matter.

I am, Gentlemen,

Your obedient Servant,

The Surveyors,
ABERDEEN.



© 2021

Secretary.

Lloyd's Register
Foundation