

by Chief Ship Surveyor 18/1/13

Received from Chief Ship Surveyor

SHIP'S NAME At St No 507

Rpt. Abr No. 10908

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

First entry

It is submitted the Aberdeen Surveyors should be informed that a report has been received from the Hull Surveyors, from which it appears that the Machinery has been fitted, but that with regard to the pillars recommended to be fitted as per Aberdeen report No. 10908, Messrs. Earles Shipbuilding & Engineering Co. who have fitted the Machinery, state that they have received no instructions to carry out this work. The Surveyors should therefore be requested to arrange with the Builders for these pillars to be fitted.

AR.

RIBN
18. 1. 13

18. 1. 13

E. C. B. G.

In view of the last date on Survey on Hull report No 25793 being the 19th Nov last, the Surveyors should be requested to state whether any steps have been taken since that date in regard to the fitting of these pillars.