

DISCLOSED

SECTION

56

Received by Chief Ship Surveyor 24.3.14

Received from Chief Ship Surveyor

VESSEL'S NAME Screw K "Arnabida" Rpt. Lis. No. 908**The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.**

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Signature of Surveyor

Condition

This vessel has been examined in drydock, the rudder pintles have been renewed and minor repairs effected.

It is submitted the vessel appears worthy to remain as classed with record of survey 3.14.

100A1 "Steam Trawler"
3.14 Lis.

MM *MM*
26.3.14

N.B. The Surveyor should be requested in similar cases to fill in the summary under the heading of "Present condition of the" ^{future}



© 2021
Lloyd's Register
Foundation

006467-006778-0074