

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

VESSEL'S NAME Vic 98 REPORT Hul. No. 53291  
Huswick No. 113325  
Hul. " 17926

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine

Compound.

If Boilers fitted with forced draught

No

Tail Shaft, If fitted with a continuous liner

No

If fitted with an outside gland of }  
approved type

Yes

This vessel's machinery ~~appears to have been built in accordance~~  
~~with the Rules and the approved plans, and it is submitted she is~~  
eligible to be classed L MC 1.46.

Note for SRL (in italics):—Approved machinery spare gear to be supplied.

© 2020

Lloyd's Register  
Foundation

006489-006504-0186