

LLOYD'S REGISTER OF SHIPPING

LLOYD'S REGISTER
 15 BATTERY PLACE
 LONDON.

REC'D 25 MAY 1920
 ANSE X

NEW YORK


May 12th, 1920.

Dear Sir:-

In connection with Seattle Report
 No. 933 on the Steamer "ROBIN GOODFELLOW", I am
 advised by the Surveyors that the thickness of the
 second deck stringer angle amidships should be 11.1
 lbs. instead of 9.8 lbs. and I shall be glad if you
 will show this on the report in question.

I am, Dear Sir,

Yours faithfully,



Secretary to the
 American Committee.

The Secretary,
 LONDON.

ACJ/AB



© 2020

Lloyd's Register
 Foundation

Referred to the Chief Ship Surveyor.

25 MAY 1920

Also for Mr. S. A. Hill to note.

M
28 5 20

Secretary
American Committee.

Secretary
LONDON.

EA/CJA

Secretary

Secretary

Secretary

Secretary

Secretary

Secretary

Secretary

© 2020

Lloyd's Register
Foundation