

Lloyd's Register of Shipping,

(MEIKAI BUILDING)

32, AKASHI-MACHI,

KOBE, January 10th, 1929.

Cert. No. 1579.

This is to Certify that at the request

of Messrs. The Kobe Steel Works, Ltd., Kobe.

the Open Hearth Steel Forgings or Castings named below ~~has~~ ^{were} examined and tested at their works on December 1st to 24th, 1928 (seven visits) and found to be as far as could be ascertained, sound and free from defect.

Five (5) Intermediate Shafts

14-7/8 inches Black diameter

Drop tests: Examined in black forged condition.

Test Mark	Tenacity Tons/sq in	Elongation % in 2"	Bend 1" x 3/4 x 180°
174 C 2655 A 1	33.3	30	GOOD
173 E 1139 B 1	30.6	35	"
175 C 2693 A 1	30.9	35	"
175 E 1146 A 2	30.8	33	"
175 E 1146 A 3	30.8	33	"

These shafts are intended for Yokohama Dockyard

Ship Nos. 173, 174 or 175 and ~~has~~ ^{has} been stamped as follows:-

Test Nos as above
LLOYDS
No. 1579

Fee Yen 150.00

Expenses 3.00

5-12-28(two) 20-12-28(one) 24-12-28(two)

A. A. Latt

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society or for any error of judgment, default, or negligence of the Surveyors, other Officers or Agents of the Society."

Lloyd's Register of Shipping

(MEI KAI BUILDING)

32, 32, AKASHI-MACHI.

KO KOBÉ, January 1929.

Cert. No. 1578.

This is to Verify that at the request

of Messrs. The Kobe Steel Works, Ltd., Kobe.

the Open Hearth Steel Forgings of Castings named below were examined and tested at their works on December 1st to 8th, 1928 (seven visits) and found to be as far as could be ascertained, sound and free from defect.

Five (5) Intermediate Shafts

14-1/8 inches Black diameter

Examiners: Examined in black forged condition.

Test Mark	Tensile Strength in Tons	Elongation % in 2"	Test Result
E 1148 A 3	30.8	33	Good
E 1148 A 2	30.8	33	"
O 8693 A 1	30.9	35	"
B 1139 B 1	30.8	35	"
O 8693 A 1	30.9	35	"
E 1148 A 1	30.8	33	"
E 1148 A 3	30.8	33	"

These shafts are intended for Yokohama Dockyard

SHIP No. 120, 121 & 122 and have been stamped as follows:-

Test nos as above

H 800-110125

120, No. 121

5-12-28 (two) 20-12-28 (one) 24-12-28 (two)

Fee Fee 100.00

Expenses 3.00

Accepted

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-
"While the Committee has their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors or in any entry in the Register Book or other publication of the Society or for any error of judgment, inadvertent or negligence of the Surveyors, other Officers or Agents of the Society."

Lloyd's Register Foundation

25/8. 26/8. 28/8. 30/8. 1/9. 2/9. 13/9. 16/9. 17/9. 19/9. 22/9. 25/9. 28/9. 1/10. 4/10. 11/10. 12/10. 15/10. 18/10. 21/10. 24/10. 27/10. 30/10.