

26.9.02

S. S. Crookes

The Surveyors appear to have overlooked forced draught being fitted when worked out the horsepower.

This will make a difference of £11:15:0 in the fees charged.

£105-0-0

C.M.

25.9.02



© 2020

Lloyd's Register
Foundation

006523-006535-0062