

Wood S.S. "WAR STIKINE"

It is submitted that the Grimsby Surveyors might be asked to forward as early as possible a report on Form 10 of the condition of the vessel's bottom when seen in dry dock.

This information is required for the Ministry of Shipping.

H.R.
14. 5. 19.



© 2021

Lloyd's Register
Foundation

006536-006551-0172