

No. of Forecastle  
No. of Houses on Deck (CHAR)  
No. of excess of Hatchways

Chief Ship Surveyor 19/4/12

Received from Chief Ship Surveyor \_\_\_\_\_

NAME *At J J Libra*

Rpt. *Dem* No. *7667*

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.

Survey *First entry*

It is submitted the Sunderland Surveyors informed that this vessel is proceeding to their port when it is stated her Machinery will be overhauled, and that in order to complete the Survey to S & B Casings require to be riveted up & the deck & way of same to be completed. The Sunderland Surveyors should be requested to fix the case the necessary attention, and on completion of the work they should forward a report on form 8 with a view to the classification of the vessel.

19/4/12

*[Signature]*

*2137*

*19/4/12*



© 2021

Lloyd's Register  
Foundation

006628-006640-0169