

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of London

No. in Reg. Book. Survey held at Date, First Survey Last Survey 19

24138 on the Wood, Iron or Steel *SK Varanus* Master

TONNAGE:- Built at *Selby* By whom *Lockhart & Sons* When *1910*

GROSS *258* Owners *Archde Stm Fishing Co Ltd.* Port belonging to *Grimsby*

UNDER DEK. *237* Owners' Address

NET *104* (if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

WB=CelLDorDBa feet; uE&B feet; f feet; } Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

total capacity tons. FPT tons; APT tons; MT feet tons. }
N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. *12150* Port *Grms*

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

CHARACTER, Date of last Survey and of Periodical Surveys.	Year Assigned for special survey.	Machinery and Boiler Surveys (including date of N.B., if any).
<i>1100 AT</i>		<i>+ LMC 4.19</i>
<i>Stm Hauler 6.21</i>		<i>TS 6.21</i>
<i>SS Grms No 2-19</i>		<i>C.L.</i>
		<i>Ad. 1.21</i>

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS :-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Renewed ...								
Removed and Fair'd or Repaired ...								
Fair'd or Repaired in place ...								

PRESENT CONDITION OF THE			
Decks	State if Tanks have been examined inside	Dbng. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Felt.)
Caulking of Decks	State if Tanks now tested	Engine Room Skylights	When put on, Month Year
Waterways	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	Boats
Coamings	Ceiling	Scuppers	Masts, Yards, &c.
Beams & Fastenings	Cement or Asphalt (State which.)	Cargo Hatchways	Condition, how ascertained (State if wedges removed)
Outside Plating	Rudder	Hatches	Sails
Caulking of ditto	Steering gear and its connections	Planking of Wood Vessels	Equipment letter
Rivets	Windlass	Caulking ditto	Anchors, No. of
Breasthooks & Crutches	Have Pumps now been examined and found efficient?	Treenails ditto	Cables (State if now ranged)
Transoms	Have Sluice Valves now been examined and found efficient?	Breasthooks & Stemson ditto	length size (on board)
Frames	Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Rule length size
Reverse Frames		Timbers of Frame at openings ditto	Hawser & Warps
Floors		Ditto ditto at other places ditto	Standing & Running Rigging
Keelsons		Stringers, Clamps & Shelves ditto	
Stringers		Salting ditto (State if examined.)	
Inner Bottom Plating	Have Ventilators and their Coamings been examined and found efficient?		

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

Survey Fee (per Section 28) £	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29) £	:	:	19
Travelling Expenses (if chargeable) £	:	:	Received by me,
Second Surveyor's Fee (if any) £	:	:	19

Committee's Minute *FRI 24 FEB. 1922*

Character Assigned *Withdraw class*

W. insert

Surveyor to Lloyd's Register of Shipping.

General Committee

Thursday, 2nd March 1922

Lloyd's Register

Classing Committee's

Foundation

decision confirmed as

If a Survey also been held on the Machinery of the Ship? If so, is the Report sent now, or when will it be sent?

006641-006653-0300

Is Certificate required? If so, to be sent to