

1

Sent to Chief Surveyors 21. 5. 24.

22 MAY 1924

VESSEL'S NAME Sc. K. Ocean Queen *(see letter)* Received from Chief Surveyors Report Final No. 13699**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/22.)

Nature of Survey 2nd No. 1 When due 7-23B.S. due 11-22.Stem bush.

The 2nd.s.s.No.1 became due 7,23.

Repairs are required to some indented topside plating and to the stem bar at the Owners' convenience.

The Gothenburg Surveyors now forward a translated copy of a letter received from the Owners, from which it appears it is not intended to continue the classification.

It is submitted the vessel's class be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw Class

Insert ...

21.5.24.



© 2021

Lloyd's Register  
Foundation

006680-006693-0323