

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

"S. S. Quino"

Rpt.

Tri.

No.

623

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

Nature of Survey

DAMAGE.

Damage through *cause not stated*

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str.	Plates	Dk.	Plates
Renewed									
Removed and faired or repaired.....									
Faired or repaired in place.....	/								

Other items:-

Bottom cleaned & coated, rudder rebushed.

Some further damage to plating & framing was noted and the Surveyor recommends repairs be effected at the next special survey

It is submitted the vessel is worthy to remain as classed with

record of Survey *6-24 Tri.* as recommended *subject as recommended.*

100A1

*Shade dk with grub.**Source in the Adriatic**6-24 Tri.**Fitted for oil fuel &c**Subject &c**NH.**30-6-24*

Lloyd's Register
Foundation