

21st February 1948.

Messrs. Trinidad Leaseholds Ltd.,  
Point-a-Pierre.

Attention Mr. Gray, Actg. Marine Supt.

Dear Sir,

Reference general examination of cargo tanks of your s.s. "IERE" on 19th inst, before a list of necessary repairs can be drawn up, the tanks will require to be chipped and scaled as follows:-

No. 1, 2 & 3 Tanks, Port & Stbd.

Deck beams and knees

Main thwartship beams

Vertical stiffeners on summer tank bulkheads

Margin brackets on floors

No. 3 Tank, Port & Stbd

Floors. (in addition to above)


Summer Tanks

Shipside frames

Deck beams and knees.

I would point out that the general condition of this vessel's cargo tanks had deteriorated considerably since last examination, and on preliminary examination, it would appear that considerable repairs will require to be effected before the vessel is in a fit state to proceed to the United Kingdom.

Yours faithfully,

(Signed) 

SURVEYOR TO LLOYD'S REGISTER OF SHIPPING.



© 2021

Lloyd's Register  
Foundation

006797-006808-0125