

Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME "ODIN" Report _____ Lon. _____

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the repairs, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5)

Date of Survey _____ When due _____

The Boiler Survey became due on this vessel at the end of October last.

In reply to enquiry, the Stockholm Surveyors now write to the effect that the Owners wish to remove the vessel from this Society's classification.

It is submitted the vessel's class be withdrawn from the Register Book and Three Dots (...) inserted in lieu thereof, indicating withdrawal of class at Owners' request.

Withdraw class. Insert ...



22.12.36.



© 2020

Lloyd's Register
Foundation

006819-006830-0131