

9m. 6.14

Sent to Chief Surveyors

20. 6. 23.

Received from Chief Surveyors

21 1923

VESSEL'S NAME

s/s Sarnolite

Report

Con.

No.

86742<sup>a</sup>

## For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

Nature of Survey

Boiler

When due

4. 23.

The boiler survey became due in 4. 23. no part has been held.

The Owners state that they do not wish to retain the vessel's class.

It is submitted that the class of the vessel be withdrawn from the Register Book & three dots inserted in lieu thereof. indicating that the class has been withdrawn at the Owners request.

Withdraw class.

Insert ...

MS  
20/6/23

MS



© 2020

Lloyd's Register  
Foundation

006819-006830-0225