

1

Sent to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

19 FEB 1929

VESSEL'S NAME Stl. Sc. "WILLIAM COWPER". Report \_\_\_\_\_ Lon. \_\_\_\_\_ No. 93560a.**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/22.*)

Nature of Survey \_\_\_\_\_ When due \_\_\_\_\_

The S.S.No.1 became due 10,28.

The Melbourne Surveyors now forward a letter from the Owners who state they do not desire to maintain the classification.

It is submitted the class of the vessel be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at Owners' request.

Withdrawn Class  
Insert ...



© 2020

Lloyd's Register  
Foundation

006831-006844-0083

19.2.29