

5m. 11/28.

Received by Chief Ship Surveyor

Received from

VESSEL'S NAME

ARAYBANK

32 that

The remarks of the Chief Ship Surveyor are desired on this case for the convenience of Belfast,

("The endorsement to contain a succinct summary of any repairs that have been required and to show to bring out clearly any exceptional features in connection with the case, so that the Classing presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

(60fms. cable require to rails, etc)

The ALEXANDRIA Survey vessel afloat and on account of damage from rails, etc or twisted deck rails (p.s.f) top edge of No. 5 (p.s) abreast foremast bent, a rigging other minor damage.

*Partial permanent repairs*  
*sheerstrake convenient* The Surveyor recommends at the first opportunity.

It is submitted that to remain as classed without record of survey recommended, and as above.

As Now, Subject etc.



© 2021

Lloyd's Register Foundation

006845-006856-0019

tra... t in above