

My opinion (which should be referred to 385)
is that provided an estimate showing that
is held & any defects which are observed
are dealt with & made satisfactory
Record of Examined LP might be
assigned

Roll



© 2021

for 6 mos
notation only
WDA

006845-006856-0102

The wear down of the tail shaft has been checked

(Ltr. 5.)

Port of DUBLIN.

21 FEB 1945
12TH

19TH FEB.

The following Reports are enclosed:

[illegible]

N.B.--This form is to be used for the advice of reports only.

© 2021

price of reports only.