

COPY

Lloyd's Register of Shipping.

MEIKAI BUILDING

32, AKASHI-MACHI,

KOBE.

28th March 1933.



CERTIFICATE OF AIR RECEIVER

No. 3434.

This is to Certify that the two Air Receivers made by Messrs. Osaka Iron Works, Ltd., Sakurajima Yard, Osaka, for Messrs. Harima Shipbuilding and Engineering Co., Yard No. 189 and marked as below, have been surveyed during construction by the undersigned. The material has been tested by the surveyors to Lloyd's Register; the scantlings are in accordance with the Society's Rules for a working pressure of 30 Kg/cm², and the workmanship is good. The Air Receivers having been tested in my presence on the 25th and 27th March 1933 by hydraulic pressure to 44 Kg/cm², showed no signs of weakness, and were found tight and sound in every respect at that pressure. Working pressure not to exceed 30 Kg/cm².

MARK ON AIR RECEIVERS.

: No. 3434	: No. 3434	:
: LLOYD'S TEST	: LLOYD'S TEST	:
: 44 KG/CM ²	: 44 KG/CM ²	:
: W.P. 30 KG/CM ²	: W.P. 30 KG/CM ²	:
: 25-3-33	: 27-3-33	:

Fee,.....Yen 100:00

Expense,.....Yen 18:00

M. G. Smith
SURVEYOR TO LLOYD'S REGISTER.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society."

Y 109

unigidē to pteinsē a'bgollē

MEIKAI BUILDING

32, AKASHI-MACHI,

KOBÉ.

THE NEW YORK PUBLIC LIBRARY

NY 100-87164 NYA NO 17AD1112B4D



1952

३५२ ॥ ३५३ ॥

tant utitur ¶ ut ei aid ¶

1. The first step is to identify the problem or question that needs to be answered. This involves understanding the context and the specific requirements of the task.

100-443887-100

and 1945 and 1946, have been entered under separate

Along as the undersigned. The material has been tested by this

with operations in the field; the results are in accordance with

and dignity, a sense for a working pressure of 10-12 kg/cm², and the

The Air Force has been asked to pay \$100,000 for the study.

Reference on Jan 28th and Feb 1st 1977 by telephone

the third time when the stream is only a brook. "To get a

For security, please do not leave your car unattended in the car park.

... 1942 ...

1953

1951年1月1日

NEW YORK: J. B. LIPPINCOTT & CO., 15 N. 2ND ST., 1877.

This Certificate is issued upon the terms of the Rules and Regulations of the Society which provide that:—