

COPY

Lloyd's Register of Shipping.



Port Kobe.

15th July 1933.

CERTIFICATE No. 3470.

This is to Certify that

A. D. Morrison,

the undersigned Surveyor to this Society did at the request of Messrs. Mitsubishi Zosen Kaisha, Ltd., Kobe, attend at their works on 28th March 1933 and subsequently for the purpose of examining and testing one 5 H.P. fuel oil service pump ordered by Kobe Steel Works, Ltd., Kobe and intended for Harima Shipbuilding and Engineering Co. Ship No. 189.

The pump casing was tested by hydraulic pressure to 3.8 Kg/cm² and found to be sound and tight.

The pump was finally connected to a motor marked:-

LLOYD'S
No. 676A
H.D.B. 1R.
19-4-33

and tried under working conditions on the 9th May 1933 and found to be satisfactory, capacity of pump 10 cubic metres /hour at 1250 R.P.M.

The pump has been stamped:

MACHINE No. 75
LLOYD'S
No. 3470
A.D.M.
9.5.33

Fee, £50:00
Expenses, £ 5:00

A. D. Morrison
SURVEYOR TO LLOYD'S REGISTER.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-

"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society."

Y T O S

quidam et regis a'gul

40

1897. *trout*



10542-91 10542-91

This is to Certify that

4-10-1944

[illegible]

ALL INFORMATION CONTAINED
HEREIN IS UNCLASSIFIED
DATE 08-11-01 BY 60322
JLH

ALL INFORMATION CONTAINED
HEREIN IS UNCLASSIFIED
DATE 08-11-01 BY 60322
JLH

RECEIVED
JAN 10 1964
U.S. DEPT. OF JUSTICE
FEDERAL BUREAU OF INVESTIGATION
WASHINGTON, D.C. 20535

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that—

"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracies in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society."

MM 8-35-C