

COPY.

Lloyd's Register of British & Foreign Shipping,

71, Fenchurch Street, E.C.

20th March, 1913.

Gentlemen,

With reference to Mr. Wilson's First Entry Report No. 25972 on the steel screw steamer "DOGGER BANK" built by Messrs. Cochrane & Sons, Ltd. (Yard No. 551), I have to request that he will be good enough to state whether he is correct in reporting that there are 165 fms. of 1" chain cable on board, in view of the Rules requiring the vessel to be supplied with 120 fms. of $1\frac{1}{8}$ " cable.

I am, Gentlemen,

Your obedient servant,

Secretary.

The Surveyors,

H U L L.



© 2021

Lloyd's Register
Foundation

006868-006876-0110