

DISCLOSED
SECTION.

Rpt. 8.

REPORT OF SURVEY FOR REPAIR

Date of writing Report... When handed in at Local Office...

No. in Survey held at...

Reg. Book.

36585

on the Wood, Iron or Steel

M/V

"A. HAGUE"

(No. of Visits)

Port of LONDON

Date, First Survey

Last Survey

TONNAGE :-

GROSS 4027

UNDER DECK 3219

NET 2450

Built at Glasgow

By whom Harland & Wolff Ltd.

Owners Glasgow French Row

(Ministère des Travaux Publics)

Managers de la Marine Marchande
Général d'Armement Maritime

(If not already recorded in Appendix to Register Book)

Port belonging to Nantes

Surveyed Afloat or in Dry Dock?

Name of Dock

Destined Voyage

Cell D Bord Ba feet ; uE & B... feet ; f... feet

total capacity tons. FPT tons ; APT tons ; MT feet tons.

Only alterations in the existing records of tanks should be inserted.

N.B. All alterations in the existing records should be underlined.

Last Report, No. 1706

Port

ALG

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER.

* for Special Survey
Date of last Survey and of
Periodical Surveys.

Machinery and Boiler
Surveys
(Including date of N.B., if any).

+100 FI with +LMR 647
freeboard. 6.47 TS. CL
Rt. Blue cold. Ref. mech.
Oil Eng.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS :-

Renewed ...
Removed and Faird or Repaired
Faird or Repaired in place

Shell Plates.

Frames.

R. Frames.

Floors and
Bracket Floors

Beams.

Inner Bottom
Plates.

Dk. Plates.

Other Items :-

PRESENT CONDITION OF THE

Decks

Caulking of Decks

Coamings

Beams & Fastenings

Outside Plating

" " in way of sidelights

Frames

Reverse Frames

Longitudinals

Transverses

Floors

Keelsons

Stringers

Inner Bottom Plating

Have the Tanks been examined internally?

Have the Tanks been tested?

Bulkheads

Ceiling

Cement or Asphalt

Rudder

Steering gear and its connections

Windlass

Have pumps been examined and found efficient?

Have Sluice Valves been examined and found efficient?

Have Watertight Doors been examined and found efficient?

Have Ventilators and their Coamings been examined and found efficient?

Air and Sounding Pipes

Doubling Plates under Sounding Pipes

Engine Room Skylights

Coal Bunkers, Openings, Covers, &c.

Oil Bunkers

Scuppers

Cargo Hatchways

Hatches

Planking

Caulking

Treenails

Breasthooks & Stemson

Transoms, Pointers & Crutches

Timbers of Frame at openings

" " at other places

Stringers, Clamps & Shelves

Salting

State if examined.

Copper, or Y.M.

(State if on Felt.)

When fitted, Month Year

Boats

Masts, Yards, &c.

Condition, how ascertained.

(State if wedges removed.)

Equipment letter

Anchors, No. of

Cables (State if

" length

General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

INTEND IN ENGLAND,
space for Committee's Minutes.

006903-006911-0228



© 2021

Lloyd's Register
Foundation