

For the information of Surveyors and the Committee only.

Received at \_\_\_\_\_ Office, \_\_\_\_\_ 19\_\_

# Lloyd's Register of Shipping.

(Report on Machinery, No. 30616 Port Sunderland)

## No. \_\_\_\_\_ ENGINE FORGINGS ~~OR CASTINGS~~.

I have to report that the Forgings or Castings, as herein described, manufactured by Messrs J.S. Forster & Sons Ltd. of Hylton for the Engines No. 2779 being constructed by North Eastern Marine Eng<sup>co</sup> of Sunderland for the Ship No. \_\_\_\_\_, being built by \_\_\_\_\_ of \_\_\_\_\_

have been inspected by me as set forth below, and found to be, so far as can be seen, sound and free from defects. These have been despatched to North Eastern Marine Eng<sup>co</sup> Ltd. Sunderland

Forgings or Castings.

Lloyd's No. 6192  
J.D.  
2-2-31  
3-2-31

Test No  
H 12 (2)  
H 13  
H 14

J. Dale  
Sunderland


	CRANK SHAFT.	THRUST SHAFT.	INTERMEDIATE SHAFTS	TUBE SHAFT.
	FLYWHEEL SHAFT.			SCREW SHAFT.
le ...	/	/	(4)	/
ed ...			S.M. Engd. steel Forged yes 8" dia	
ns, Forgings			Forging & testing	
Castings				
on } tion }				
Standard Pieces.				
Test—				
square inch			Test No H 12    H 13    H 14	
per cent			30.1    28.1    28.8	
ding Test—			34%    32%    31%	
fore fracture			180°    180°    180°	
en Inspected			22-1-31 to 3-2-31	

PARTICULARS OF OTHER TESTS APPLIED TO CASTINGS:—

any chargeable) £ \_\_\_\_\_

To be paid at \_\_\_\_\_

wrought iron, state whether piled bars or scrap. If of steel, state whether made by the Open Hearth process.



Travelling Expenses (if chargeable).....

Received by me, 8 April 1931

006996-007007-0123

Committee's Minute

PM. 24 FEB 1931

Engineer Surveyor to

Assigned