

1

Sent to Chief Surveyors 16. 1. 26.

18 JAN 1926

VESSEL'S NAME

s/s "Gladys."

Received from Chief Surveyors

Report L.A.

No. 89572A

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Boiler

When due

4. 25.

The boiler survey became due 4. 25. no part has been held.

The Owners now state that they do not intend to continue the vessel's class.

It is submitted that the vessel's class be withdrawn from the Register Book a three dots inserted in lieu thereof, indicating that the class has been withdrawn at the Owner's request.

Withdraw class.
Insert ...

KID
16/1/26
CWS

W.L.B.

© 2020

Lloyd's Register
Foundation