

to Chief Surveyors _____

Received from Chief Surveyors 16 JUN 1926

VESSEL'S NAME *Steam Trawler "Serfib."*Report *Lon.* No. *90123A.***For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey _____

When due _____

The Boiler Survey became due in 1.26 & the Screw Shaft Survey in 4.26.

In reply to enquiry the Owners have informed the Society's Surveyor at Auckland, N.Z. that they wish the vessel to be withdrawn from classification.

It is submitted the vessel's class be withdrawn from the Register Book & three dots inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw Class
Insert ...

[Signature]

[Signature]
14/6/26

[Signature]

[Signature]

[Signature]



© 2020

Lloyd's Register
Foundation

007008-007020-0223